

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**

**WATER QUALITY REPORT**

**MAY 2014**

RUN DATE: June 6, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	63	61	62	60.8	58.5	59.5	9.7	9.4	9.6
2	63	62	62	60.2	58.5	59.3	9.8	9.6	9.7
3	68	62	64	59.7	58.2	58.8	9.9	9.7	9.8
4	65	63	64	59.6	57.8	58.6	9.9	9.7	9.8
5	67	63	64	59.3	58.0	58.5	9.9	9.7	9.8
6	64	58	61	58.7	57.2	57.9	10.0	9.7	9.8
7	60	58	59	58.8	57.0	57.8	10.0	9.8	9.9
8	61	58	59	58.9	57.4	58.1	10.1	9.8	9.9
9	61	60	60	59.8	57.6	58.6	10.1	9.8	9.9
10	63	59	61	59.6	57.9	58.7	10.0	9.7	9.8
11	61	59	60	59.3	57.3	58.2	10.0	9.7	9.9
12	61	60	61	60.4	58.0	59.1	9.9	9.6	9.8
13	68	60	62	61.1	59.0	59.9	9.9	9.6	9.7
14	64	59	62	61.6	59.4	60.4	9.8	9.5	9.6
15	65	59	62	62.0	59.5	60.7	9.8	9.3	9.6
16	68	62	65	62.5	60.1	61.3	9.5	9.1	9.4
17	73	66	68	63.0	60.4	61.9	9.3	8.7	9.1
18	79	72	75	64.7	61.3	62.9	8.8	8.6	8.7
19	81	71	75	64.8	62.4	63.6	8.9	8.6	8.8
20	79	69	72	63.7	61.7	62.8	9.3	8.8	9.1
21	69	68	68	64.6	61.0	62.8	9.5	9.2	9.4
22	74	67	68	66.5	62.8	64.6	9.4	9.0	9.2
23	79	67	71	68.7	64.4	66.5	9.0	8.6	8.9
24	91	70	79	70.1	66.4	68.1	8.9	8.5	8.7
25	90	72	77	70.8	67.1	69.0	8.8	8.5	8.7
26	98	73	83	71.9	68.0	69.8	8.6	8.2	8.5
27	96	76	86	72.0	68.3	70.1	8.6	8.2	8.3
28	93	72	78	70.5	67.5	69.1	8.8	8.3	8.5
29	85	72	75	70.2	66.2	68.2	9.0	8.5	8.7
30	99	72	78	70.3	66.3	68.2	9.0	8.6	8.8
31	118	74	84	70.9	66.1	68.4	9.0	8.5	8.7

Comments:

0 reading indicates that the station was out of service.