

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**

**WATER QUALITY REPORT**

**MAY 2015**

RUN DATE: June 1, 2015

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	85	80	82	78.2	70.2	74.0	8.1	7.5	7.7
2	102	83	87	78.4	70.7	74.4	8.1	7.5	7.7
3	117	82	94	77.2	70.1	73.6	8.2	7.6	7.8
4	103	83	94	75.9	69.0	72.2	8.2	7.7	7.9
5	116	77	94	74.5	67.5	70.8	8.8	7.9	8.3
6	92	79	85	73.9	67.1	70.3	9.0	8.2	8.5
7	84	79	81	70.4	66.6	67.9	8.9	8.1	8.5
8	82	77	79	71.6	64.5	67.6	9.3	8.5	8.8
9	107	81	87	73.1	65.7	69.1	9.2	8.0	8.7
10	88	79	83	74.6	66.4	70.3	9.1	7.8	8.5
11	81	76	78	73.9	66.8	70.2	8.9	8.2	8.4
12	119	77	88	72.9	65.8	69.0	9.1	8.2	8.5
13	82	78	79	72.4	65.2	68.5	9.2	8.3	8.6
14	103	76	79	69.6	65.8	67.6	9.1	8.3	8.6
15	93	76	80	71.5	64.7	67.5	9.3	8.5	8.8
16	81	76	77	73.3	64.5	68.6	9.2	8.4	8.7
17	79	75	77	70.8	66.5	68.5	9.2	8.3	8.7
18	96	76	85	71.0	65.6	67.8	9.3	8.5	8.8
19	92	77	83	73.0	64.2	68.2	9.4	8.4	8.8
20	101	80	85	74.5	66.1	69.9	9.1	8.3	8.6
21	127	82	91	71.8	66.6	69.2	9.1	8.2	8.6
22	117	83	87	73.5	65.8	69.2	9.3	8.4	8.7
23	88	81	84	75.3	67.1	70.8	9.1	8.2	8.6
24	91	83	87	77.0	67.9	72.1	9.0	8.0	8.4
25	102	84	92	77.6	69.1	73.1	8.8	7.9	8.2
26	90	84	87	77.9	69.0	73.2	8.8	7.8	8.2
27	94	87	90	78.6	69.2	73.7	8.8	7.8	8.2
28	129	85	95	77.2	69.9	73.6	8.9	7.7	8.2
29	124	84	97	79.2	69.8	74.4	8.9	7.7	8.2
30	91	84	88	79.8	71.3	75.5	8.8	7.5	8.0
31	92	84	87	78.3	71.7	75.2	8.7	7.5	8.0

Comments:

0 reading indicates that the station was out of service.