

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

WATER QUALITY REPORT

JUNE 2011

RUN DATE: July 25, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	75	67	68	57.6	56.2	56.9	9.7	9.4	9.6
2	73	67	69	57.2	55.1	56.2	9.8	9.6	9.7
3	74	67	69	57.2	56.0	56.7	9.8	9.5	9.6
4	73	67	69	56.3	55.4	55.7	9.6	9.4	9.5
5	75	66	69	57.0	54.7	55.6	9.7	9.4	9.6
6	69	66	67	57.2	56.0	56.7	9.6	9.4	9.5
7	69	65	67	57.8	55.3	56.4	9.7	9.6	9.7
8	71	65	66	58.7	56.5	57.5	9.7	9.4	9.6
9	66	61	64	59.0	57.0	58.0	9.6	9.4	9.5
10	69	60	64	59.9	57.6	58.7	9.6	9.4	9.5
11	63	62	63	59.2	57.6	58.3	9.6	9.4	9.5
12	68	62	65	59.2	56.8	57.9	9.7	9.5	9.6
13	63	62	63	60.2	57.7	58.9	9.6	9.4	9.5
14	68	62	65	61.8	58.6	60.0	9.5	9.2	9.4
15	65	63	64	61.9	59.1	60.4	9.5	9.1	9.3
16	70	63	67	61.7	59.3	60.3	9.4	9.1	9.3
17	64	62	63	61.4	58.8	60.0	9.4	9.1	9.3
18	71	62	65	61.1	58.8	59.9	9.4	9.2	9.3
19	71	63	66	61.2	58.6	59.9	9.4	9.2	9.3
20	64	62	63	61.8	59.3	60.4	9.4	9.1	9.2
21	66	63	64	62.1	59.7	60.8	9.3	9.1	9.2
22	69	63	66	62.6	59.9	61.2	9.3	9.0	9.1
23	64	62	63	62.4	59.9	61.1	9.3	9.0	9.1
24	69	63	65	61.7	58.9	60.3	9.3	9.1	9.2
25	69	64	66	61.4	58.9	60.1	9.4	9.1	9.2
26	65	62	64	61.6	59.0	60.2	9.4	9.1	9.2
27	68	62	64	62.1	59.0	60.5	9.3	9.0	9.2
28	70	62	65	61.0	59.6	60.4	9.3	8.9	9.1
29	74	62	65	59.9	58.0	58.9	9.3	9.0	9.2
30	63	62	63	60.7	58.1	59.3	9.4	9.2	9.3

Comments:

0 reading indicates that the station was out of service.