

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**

**WATER QUALITY REPORT**

**JUNE 2014**

RUN DATE: July 31, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	104	76	85	73.1	67.6	70.2	8.8	8.2	8.5
2	110	75	85	74.0	69.3	71.5	8.7	8.1	8.3
3	111	76	87	73.7	68.8	71.3	8.8	8.1	8.4
4	109	77	86	75.0	69.4	72.1	8.8	8.1	8.4
5	103	79	85	76.9	71.0	73.7	8.5	7.9	8.1
6	96	77	82	77.3	71.8	74.4	8.5	7.7	8.0
7	95	77	87	78.3	72.5	75.3	8.4	7.6	7.9
8	86	78	81	79.8	73.6	76.5	8.3	7.5	7.8
9	101	76	84	81.2	75.0	78.0	7.9	7.2	7.5
10	131	78	95	80.9	76.5	78.4	7.9	7.0	7.4
11	99	75	83	79.0	74.4	76.6	8.2	7.1	7.6
12	116	72	82	77.3	72.7	74.9	8.4	7.4	7.8
13	79	69	71	75.8	70.7	73.3	8.6	7.7	8.1
14	80	70	72	75.5	70.9	73.2	8.6	7.7	8.1
15	99	70	77	75.2	70.2	72.7	8.6	7.8	8.1
16	99	75	82	74.5	69.9	72.1	8.7	7.9	8.2
17	99	75	84	74.1	68.7	71.3	8.8	8.0	8.3
18	97	74	83	75.5	69.3	72.3	8.7	7.9	8.3
19	105	72	83	77.2	70.5	73.8	8.7	7.8	8.2
20	90	72	78	78.6	72.4	75.1	8.6	7.8	8.1
21	81	73	76	75.8	72.6	74.3	8.4	7.7	8.0
22	91	73	77	76.6	70.1	73.2	8.6	7.9	8.2
23	129	73	80	77.2	70.9	73.9	8.5	7.8	8.1
24	126	79	93	79.1	72.7	75.6	8.2	7.6	7.8
25	110	81	91	78.7	73.6	76.0	8.1	7.4	7.7
26	105	81	87	78.6	73.0	75.6	8.1	7.2	7.7
27	96	75	82	79.3	72.6	75.7	8.2	7.4	7.7
28	82	75	77	80.0	73.2	76.4	8.1	7.3	7.6
29	80	75	77	80.2	74.0	77.0	8.0	7.3	7.6
30	87	72	78	81.2	75.3	78.2	8.1	7.1	7.5

Comments:

0 reading indicates that the station was out of service.