

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

JUNE 2019

WATER QUALITY REPORT

RUN DATE: July 1, 2019

ELECTRICAL CONDUCTIVITY, UMHOS				WATER TEMPERATURE, DEG			DISSOLVED OXYZEN, PPM		
DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
2	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
3	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
4	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
5	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
6	58	56	57	62.4	59.6	61.0	9.8	9.3	9.5
7	59	58	58	61.8	59.3	60.6	9.6	9.4	9.5
8	62	59	60	62.0	58.7	60.3	9.5	9.3	9.4
9	63	60	61	63.2	60.0	61.7	9.4	9.1	9.3
10	63	60	61	64.3	62.1	63.3	9.2	8.9	9.1
11	60	57	58	63.4	61.0	61.9	9.6	9.2	9.5
12	58	57	57	63.3	60.2	61.7	9.7	9.3	9.5
13	58	57	58	64.2	61.1	62.6	9.5	9.2	9.4
14	59	57	58	64.0	61.5	62.8	9.4	9.2	9.3
15	60	58	60	63.6	61.1	62.6	9.4	9.1	9.2
16	61	60	61	64.7	61.6	63.1	9.3	8.9	9.1
17	64	61	62	65.8	62.6	64.3	9.0	8.8	8.9
18	62	59	60	65.0	62.2	63.9	9.3	8.9	9.2
19	61	59	60	65.9	62.7	64.3	9.3	9.0	9.2
20	59	54	57	64.1	59.9	61.4	9.7	9.3	9.5
21	56	55	55	61.9	60.2	61.1	9.7	9.4	9.5
22	60	55	57	63.5	60.0	61.7	9.7	8.8	9.3
23	62	60	61	66.0	61.9	64.0	8.9	8.6	8.8
24	61	59	61	65.7	63.3	64.8	9.0	8.6	8.8
25	58	55	56	64.1	59.3	60.6	9.8	9.1	9.7
26	57	56	56	61.2	59.7	60.3	9.9	9.6	9.7
27	57	56	57	61.0	59.2	60.0	9.9	9.6	9.8
28	60	57	57	60.0	58.4	59.4	9.9	9.7	9.8
29	63	58	60	60.6	57.4	59.0	10.0	9.1	9.6
30	64	62	63	64.0	60.0	61.9	9.1	8.8	9.0

Comments:

0 reading indicates that the station was out of service.