

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

JULY 2013

WATER QUALITY REPORT

RUN DATE: October 25, 2013

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	75	63	68	78.4	74.6	76.7	8.6	7.8	8.1
2	71	64	67	78.6	74.8	76.9	8.6	8.0	8.3
3	74	67	69	77.6	74.3	76.2	8.7	8.1	8.4
4	74	66	69	78.7	74.4	76.5	8.7	8.1	8.4
5	74	66	68	77.7	73.8	75.9	8.7	8.1	8.4
6	87	65	71	76.4	72.2	74.4	8.9	8.3	8.5
7	99	74	78	76.6	71.8	74.2	8.9	8.3	8.5
8	79	69	72	76.9	72.2	74.4	8.9	8.3	8.6
9	75	64	69	77.5	72.1	74.8	8.9	7.8	8.4
10	74	64	68	76.5	72.8	74.8	8.2	7.7	7.9
11	76	66	69	77.0	71.5	74.2	8.3	7.8	8.0
12	76	68	70	76.9	71.3	74.0	8.3	7.8	8.0
13	77	68	70	77.6	71.8	74.6	8.3	7.7	8.0
14	78	69	72	78.0	72.5	75.1	8.2	7.7	7.9
15	106	70	77	77.2	72.1	74.7	8.2	7.7	7.9
16	106	71	78	76.1	71.4	73.7	8.3	7.7	8.0
17	76	68	71	75.9	70.3	73.1	8.5	7.8	8.1
18	81	69	72	76.9	71.0	73.9	8.4	7.8	8.1
19	75	67	70	77.7	71.8	74.6	8.3	7.7	8.0
20	76	68	70	78.1	72.8	75.4	8.2	7.6	7.9
21	81	68	74	79.1	73.6	76.2	8.1	7.5	7.7
22	79	70	74	76.8	73.5	75.3	8.1	7.5	7.8
23	82	67	72	75.0	72.7	73.9	8.4	7.7	8.0
24	77	67	69	76.3	70.6	73.3	8.5	7.9	8.2
25	112	70	80	77.7	71.8	74.6	8.4	7.8	8.1
26	110	68	76	78.7	73.1	75.9	8.1	7.5	7.8
27	75	67	70	79.1	73.4	76.2	8.1	7.4	7.7
28	76	65	70	78.4	73.6	76.0	8.0	7.3	7.6
29	74	67	70	76.8	72.6	74.7	8.2	7.5	7.8
30	77	67	72	75.7	71.4	73.3	8.4	7.7	8.0
31	73	67	69	76.6	71.1	73.7	8.3	7.9	8.1

Comments:

0 reading indicates that the station was out of service.