

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER
WATER QUALITY REPORT

JULY 2019

RUN DATE: August 1, 2019

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	63	61	62	64.8	61.4	63.2	9.2	8.9	9.0
2	60	55	57	63.3	58.8	60.1	10.0	9.3	9.8
3	57	55	56	61.3	58.6	59.9	10.1	9.7	9.9
4	60	56	58	63.2	59.2	61.2	9.9	8.7	9.4
5	68	60	65	67.1	62.8	64.8	8.7	8.2	8.5
6	72	67	69	69.1	65.9	67.5	8.4	8.1	8.2
7	69	64	66	68.8	66.5	67.6	8.6	8.1	8.3
8	66	65	66	68.2	65.1	66.6	8.7	8.2	8.5
9	65	57	59	66.1	59.4	61.6	9.9	8.6	9.5
10	58	56	57	61.6	59.6	60.5	10.0	9.6	9.8
11	58	56	57	62.1	60.2	61.0	9.9	9.5	9.7
12	58	56	57	62.0	60.1	60.9	9.8	9.5	9.7
13	60	55	58	63.7	60.0	61.8	9.8	9.1	9.4
14	61	58	59	65.6	61.9	63.7	9.2	8.6	8.9
15	62	58	60	66.5	63.8	65.2	9.0	8.6	8.8
16	60	56	57	65.3	60.1	61.5	9.8	9.1	9.6
17	56	55	56	61.8	60.3	60.9	9.8	9.5	9.6
18	56	54	55	61.8	60.1	60.8	9.9	9.5	9.7
19	54	53	53	61.9	59.9	60.8	9.9	9.5	9.7
20	57	54	55	63.3	59.9	61.5	9.8	9.2	9.5
21	60	55	58	65.5	61.6	63.6	9.2	8.7	9.0
22	61	58	59	66.3	63.3	65.1	9.0	8.7	8.9
23	58	54	55	65.2	59.8	61.5	9.9	9.1	9.7
24	55	54	55	61.7	59.4	60.4	10.0	9.6	9.8
25	56	55	56	62.8	60.3	61.3	9.9	9.4	9.7
26	56	55	56	62.0	60.0	60.9	9.9	9.5	9.7
27	59	56	57	63.4	60.3	61.8	9.8	9.2	9.5
28	63	58	61	65.5	61.4	63.6	9.2	8.6	8.9
29	62	60	61	66.9	64.0	65.7	9.0	8.6	8.8
30	60	56	57	64.9	59.7	61.0	9.9	9.1	9.7
31	58	42	54	61.4	59.7	60.4	10.0	9.6	9.8

Comments:

0 reading indicates that the station was out of service.