



Ripon on the Stanislaus River Water Quality

Period: July 2022 Run Date: 11/22/2022

Electrical Conductivity, UMHOS				WATER TEMPERATURE, DEG			DISSOLVED OXYZEN, PPM		
Day	High	Low	Mean	High	Low	Mean	High	Low	Mean
1	77	67	71	69.8	64.7	67.4	9.4	8.6	9.0
2	80	69	71	71.5	66.4	68.8	9.1	8.1	8.6
3	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
4	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
5	0	0	0	0.0	0.0	0.0	0.0	0.0	0.0
6	80	71	72	77.5	71.9	74.5	8.6	7.5	8.0
7	72	71	71	77.3	71.2	74.1	8.7	7.6	8.0
8	97	71	78	78.1	71.7	74.7	8.7	7.6	8.1
9	76	70	71	78.2	71.9	75.0	8.7	7.6	8.1
10	80	70	72	78.7	72.2	75.4	8.7	7.6	8.0
11	83	70	71	79.9	73.6	76.6	8.6	7.5	7.9
12	72	70	71	80.2	74.0	77.0	8.4	7.3	7.8
13	82	71	74	79.4	73.4	76.3	8.6	7.4	7.9
14	97	71	77	79.8	73.1	76.3	8.6	7.5	7.9
15	76	71	72	78.9	72.6	75.7	8.7	7.5	8.0
16	85	71	73	80.0	73.3	76.7	8.6	7.6	8.0
17	87	71	73	80.2	74.5	77.2	8.6	7.4	7.9
18	91	72	80	81.7	75.0	78.1	8.5	7.4	7.8
19	89	72	79	81.3	75.1	78.0	8.5	7.3	7.8
20	92	74	80	79.9	74.2	76.9	8.7	7.4	7.9
21	74	72	73	79.5	72.7	76.0	8.8	7.6	8.1
22	85	71	73	79.2	72.6	75.7	8.8	7.6	8.1
23	85	71	72	78.2	71.7	74.9	8.8	7.7	8.1
24	72	70	71	78.8	72.1	75.3	8.8	7.7	8.1
25	81	69	71	78.3	72.3	75.3	8.8	7.6	8.1
26	71	70	71	78.6	72.6	75.5	8.8	7.6	8.1
27	81	70	72	78.2	72.2	75.1	8.8	7.7	8.2
28	83	69	71	78.3	71.9	75.0	8.9	7.7	8.2
29	78	70	72	79.1	72.4	75.7	8.8	7.6	8.1
30	87	71	74	80.6	73.7	77.0	8.6	7.4	7.9
31	76	71	73	79.5	75.2	77.0	8.6	7.3	7.8

COMMENT(S):

0 reading indicates that the station was out of service.