

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

AUGUST 2007

WATER QUALITY REPORT

RUN DATE: September 11, 2007

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	81	67	71	75.6	71.5	73.5	8.7	8.2	8.4
2	88	68	72	75.5	71.0	73.4	8.9	8.2	8.5
3	85	66	70	75.8	71.1	73.5	8.7	8.1	8.4
4	89	67	71	76.3	71.7	74.0	8.5	7.9	8.2
5	77	69	72	74.5	70.9	72.8	8.6	7.9	8.3
6	92	68	71	72.3	68.8	70.6	9.2	8.4	8.8
7	71	65	68	71.6	67.6	69.7	9.3	8.7	9.0
8	91	66	72	72.2	67.8	69.8	9.2	8.6	8.9
9	94	68	73	73.1	68.4	70.8	9.1	8.4	8.7
10	93	69	75	74.2	69.6	71.7	8.9	8.3	8.5
11	86	68	72	73.7	69.4	71.6	8.8	8.2	8.5
12	83	73	76	73.3	68.3	70.8	8.9	8.4	8.6
13	92	69	73	73.2	68.5	71.0	9.0	8.3	8.7
14	90	72	75	73.8	68.7	71.2	8.9	8.3	8.6
15	98	73	77	74.3	69.5	71.7	8.8	8.3	8.5
16	91	74	78	74.6	69.5	71.8	8.7	8.1	8.4
17	86	73	76	73.6	68.7	71.2	8.8	8.2	8.5
18	82	76	77	73.8	68.8	71.2	8.8	8.2	8.5
19	89	72	77	73.3	68.4	70.8	9.0	8.3	8.6
20	87	74	78	75.0	69.8	72.0	8.6	8.2	8.4
21	85	76	80	76.7	71.3	73.8	8.3	7.6	8.0
22	99	74	79	77.6	72.8	74.6	8.6	7.6	7.9
23	93	71	75	76.8	72.7	74.7	8.4	7.9	8.2
24	85	63	72	76.5	72.2	74.3	8.3	7.6	8.1
25	81	73	78	76.4	71.9	74.2	8.4	7.6	7.9
26	94	75	80	76.2	71.4	73.7	8.3	7.7	7.9
27	107	75	80	76.2	71.4	73.7	8.8	7.7	8.0
28	99	73	78	76.8	72.0	73.9	8.5	7.9	8.1
29	114	75	83	78.2	73.2	75.5	8.4	7.1	7.9
30	105	75	84	78.6	74.1	76.3	8.4	7.6	7.9
31	97	76	81	78.5	74.7	76.5	8.3	7.4	7.7

Comments:

0 reading indicates that the station was out of service.