

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

AUGUST 2011

WATER QUALITY REPORT

RUN DATE: September 22, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	62	61	61	63.3	60.7	61.9	9.1	8.8	9.0
2	62	60	61	65.3	60.4	62.7	9.2	8.6	8.9
3	69	63	67	68.2	63.1	65.2	8.8	8.3	8.6
4	68	62	64	75.4	63.0	67.2	8.8	6.2	8.0
5	70	58	65	75.7	61.0	70.2	9.3	4.3	6.4
6	66	58	61	62.3	59.8	60.9	9.5	9.2	9.4
7	67	59	62	62.1	59.7	60.8	9.5	9.2	9.4
8	59	58	59	62.0	59.5	60.7	9.5	9.2	9.4
9	59	58	59	62.0	59.4	60.6	9.5	9.2	9.4
10	64	58	61	62.1	59.4	60.6	9.6	9.2	9.4
11	60	58	59	62.0	59.3	60.6	9.5	9.2	9.4
12	64	58	60	61.6	59.3	60.3	9.6	9.2	9.4
13	63	59	61	61.7	59.2	60.3	9.6	9.2	9.4
14	60	59	59	61.9	59.3	60.5	9.6	9.2	9.4
15	64	59	61	61.6	59.1	60.4	9.5	9.2	9.4
16	63	59	60	61.6	59.2	60.3	9.5	9.2	9.4
17	59	58	59	61.8	58.9	60.3	9.6	9.2	9.4
18	64	58	61	62.9	60.1	61.0	9.5	9.2	9.4
19	59	58	59	61.0	58.9	59.9	9.5	9.2	9.4
20	65	58	60	60.8	58.5	59.7	9.5	9.2	9.4
21	65	59	61	60.8	58.7	59.7	9.5	9.2	9.4
22	60	59	59	60.8	58.6	59.7	9.5	9.2	9.4
23	66	59	61	60.8	58.7	59.7	9.5	9.2	9.4
24	59	59	59	60.9	58.5	59.7	9.5	9.2	9.4
25	66	59	61	60.9	58.6	59.8	9.5	9.2	9.4
26	65	60	61	61.2	59.0	60.0	9.4	9.1	9.3
27	61	59	60	61.0	58.8	59.9	9.5	9.2	9.3
28	69	60	62	60.9	58.4	59.6	9.5	9.2	9.4
29	73	62	66	62.6	58.8	60.6	9.4	8.1	8.9
30	89	73	83	64.9	61.2	63.1	8.0	7.2	7.5
31	95	87	91	66.6	63.9	65.2	7.5	7.2	7.3

Comments:

0 reading indicates that the station was out of service.