

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

AUGUST 2013

WATER QUALITY REPORT

RUN DATE: February 19, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	76	68	70	76.2	70.4	73.2	8.4	7.9	8.1
2	79	69	71	76.3	70.3	73.1	8.3	7.8	8.0
3	72	68	69	76.5	70.8	73.5	8.3	7.8	8.1
4	75	70	72	76.8	71.0	73.8	8.3	7.8	8.0
5	76	71	73	76.7	71.1	73.8	8.3	7.8	8.0
6	92	72	77	76.2	70.9	73.4	8.3	7.8	8.0
7	104	72	81	75.9	70.7	73.1	8.4	7.8	8.1
8	73	67	71	75.9	71.0	73.1	8.4	7.9	8.1
9	77	70	73	75.7	70.2	72.8	8.5	7.9	8.1
10	88	71	77	76.3	70.6	73.3	8.3	7.9	8.1
11	75	69	71	76.5	71.1	73.6	8.3	7.8	8.0
12	75	69	70	77.1	71.6	74.1	8.2	7.7	7.9
13	79	69	71	77.6	71.9	74.6	8.1	7.5	7.8
14	82	69	73	78.1	72.1	74.9	8.1	7.5	7.7
15	80	71	76	78.6	72.4	75.3	8.4	7.4	7.7
16	107	74	80	79.4	73.6	76.2	7.9	7.3	7.6
17	99	74	78	77.9	73.7	75.6	7.9	7.3	7.6
18	85	73	77	77.6	73.4	75.4	7.9	7.3	7.6
19	93	72	80	78.7	73.8	76.0	7.9	7.3	7.5
20	104	78	84	78.8	74.2	76.5	7.8	7.2	7.5
21	89	72	79	78.0	73.1	75.5	7.9	7.3	7.5
22	89	74	82	77.0	72.2	74.5	8.0	7.3	7.6
23	78	73	75	75.7	70.8	73.2	8.2	7.5	7.8
24	80	72	75	75.5	70.6	72.9	8.2	7.7	7.9
25	89	73	78	76.9	71.1	73.7	8.2	7.5	7.8
26	93	74	80	76.8	71.9	74.3	7.9	7.4	7.7
27	81	74	77	76.5	71.5	73.8	8.0	7.4	7.7
28	88	78	83	77.0	71.7	74.1	8.0	7.4	7.7
29	83	78	80	77.5	72.1	74.6	7.9	7.4	7.6
30	81	77	79	77.7	72.4	74.9	8.0	7.4	7.7
31	101	83	90	77.8	73.4	75.5	7.9	7.4	7.6

Comments:

0 reading indicates that the station was out of service.