

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

WATER QUALITY REPORT

AUGUST 2014

RUN DATE: September 2, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	74	68	71	80.3	74.2	77.2	8.0	7.5	7.8
2	107	69	79	79.6	74.6	77.2	8.0	7.5	7.7
3	102	70	79	77.3	74.3	75.6	8.2	7.5	7.8
4	108	72	84	74.7	72.0	72.8	8.4	7.9	8.1
5	88	73	80	75.0	69.9	72.2	8.6	8.1	8.4
6	79	70	75	78.2	73.0	75.2	8.3	7.8	8.1
7	78	73	75	79.8	74.1	76.8	8.2	7.3	7.9
8	87	76	79	80.6	74.4	77.3	7.9	7.5	7.6
9	92	72	79	79.4	74.0	76.7	8.1	7.5	7.8
10	94	73	79	77.0	72.6	75.1	8.4	7.8	8.1
11	101	74	82	78.1	72.7	75.2	8.3	7.8	8.1
12	93	74	80	78.0	72.8	75.3	8.3	7.7	8.0
13	94	72	77	78.1	72.6	75.2	8.3	7.8	8.0
14	116	74	79	79.6	73.3	76.2	8.2	7.7	7.9
15	85	76	79	80.4	74.1	77.1	8.1	7.6	7.8
16	88	78	82	80.4	74.3	77.2	8.2	7.6	7.9
17	97	78	81	79.8	73.8	76.7	8.2	7.6	7.9
18	106	79	88	79.5	74.0	76.6	8.2	7.6	7.9
19	109	83	93	78.8	73.6	76.1	8.3	7.5	7.9
20	105	82	88	78.9	73.3	75.9	8.4	7.5	7.9
21	89	82	85	79.1	72.9	75.8	8.4	7.6	8.0
22	119	80	90	80.3	73.6	76.7	8.3	7.6	7.9
23	109	83	90	79.6	73.2	76.3	8.4	7.5	7.9
24	86	80	82	79.6	73.0	76.2	8.4	7.5	7.9
25	90	83	85	78.4	73.1	75.6	8.3	7.5	7.9
26	109	87	95	78.8	71.8	75.2	8.4	7.7	8.0
27	100	85	91	80.3	73.3	76.7	8.3	7.6	7.9
28	97	83	89	81.1	74.3	77.6	8.2	7.5	7.7
29	92	86	89	79.2	74.2	76.9	8.2	7.3	7.7
30	93	86	89	80.6	73.1	76.7	8.2	7.6	7.8
31	101	88	93	80.2	73.7	76.8	8.2	7.4	7.7

Comments:

0 reading indicates that the station was out of service.