

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

AUGUST 2018

WATER QUALITY REPORT

RUN DATE: September 6, 2018

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	67	63	64	77.2	71.6	74.2	8.5	7.9	8.1
2	68	64	66	77.1	71.6	74.2	8.4	7.8	8.1
3	75	65	69	76.3	71.5	73.8	8.5	7.8	8.1
4	74	64	67	76.3	71.6	73.6	8.5	7.9	8.2
5	76	67	70	75.3	70.6	72.8	8.6	8.0	8.2
6	72	66	69	73.9	70.6	72.1	8.7	8.1	8.4
7	70	65	67	74.0	69.8	71.7	8.7	8.2	8.4
8	81	66	71	74.3	70.0	72.2	8.8	8.1	8.4
9	70	65	68	76.0	70.9	73.3	8.6	8.0	8.3
10	71	52	61	77.0	72.5	74.4	8.5	7.9	8.1
11	56	52	54	77.1	72.1	74.4	8.4	7.8	8.1
12	61	53	56	76.7	71.5	74.0	8.4	7.8	8.1
13	58	52	55	76.2	71.4	73.7	8.5	7.9	8.2
14	59	53	55	75.5	70.9	73.0	8.5	7.9	8.2
15	57	53	55	74.8	70.0	72.3	8.6	8.1	8.3
16	57	53	55	75.2	70.2	72.7	8.6	8.1	8.3
17	59	54	56	76.3	71.0	73.5	8.5	8.0	8.2
18	77	54	60	76.7	71.6	74.0	8.4	7.9	8.1
19	66	56	59	76.2	71.6	73.7	8.5	7.9	8.2
20	64	56	59	75.1	70.8	72.9	8.6	8.0	8.2
21	60	55	57	73.4	69.8	71.7	8.7	8.1	8.4
22	62	56	59	73.3	68.9	71.1	8.8	8.3	8.5
23	61	55	57	73.0	68.6	70.7	8.8	8.3	8.5
24	66	57	62	72.3	68.2	70.3	9.0	8.3	8.6
25	72	63	67	72.1	68.3	70.1	9.0	8.4	8.6
26	73	64	67	72.3	68.1	70.0	9.0	8.4	8.7
27	71	64	67	72.3	67.9	70.1	9.0	8.4	8.6
28	75	65	70	72.7	68.5	70.4	8.9	8.3	8.6
29	80	66	71	73.1	68.4	70.5	8.9	8.3	8.6
30	72	66	68	72.6	68.0	70.1	9.0	8.4	8.6
31	76	66	72	72.2	68.2	70.1	9.0	8.4	8.7

Comments:

0 reading indicates that the station was out of service.