

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

AUGUST 2019

WATER QUALITY REPORT

RUN DATE: September 10, 2019

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	53	51	53	61.5	59.6	60.4	10.0	9.6	9.8
2	54	53	54	61.6	59.7	60.5	10.0	9.6	9.8
3	57	54	56	63.6	59.8	61.6	9.9	9.0	9.5
4	63	57	61	65.7	61.4	63.6	9.0	8.3	8.7
5	64	61	63	66.6	64.7	65.6	8.7	8.3	8.6
6	61	54	56	65.4	59.7	61.3	9.9	8.8	9.6
7	55	54	55	61.4	59.3	60.3	10.0	9.6	9.8
8	56	55	55	61.1	59.5	60.2	9.9	9.6	9.8
9	56	56	56	60.6	59.0	59.7	10.0	9.7	9.8
10	60	56	58	62.2	59.0	60.6	10.0	9.2	9.6
11	65	58	62	65.0	60.8	62.9	9.2	8.5	8.9
12	65	58	61	66.6	63.6	65.3	8.9	8.5	8.7
13	58	50	53	65.8	60.1	61.7	10.1	9.0	9.8
14	51	50	51	61.9	59.4	60.5	10.2	9.8	10.0
15	52	51	51	61.8	59.8	60.7	10.2	9.8	10.0
16	52	51	51	62.3	59.7	61.0	10.2	9.7	9.9
17	55	51	53	63.6	59.8	61.7	10.0	9.0	9.5
18	64	55	59	65.9	62.3	64.2	9.0	8.4	8.7
19	65	61	63	67.3	64.6	65.9	8.8	8.4	8.6
20	62	60	61	67.6	64.4	66.1	8.9	8.5	8.7
21	65	60	61	68.0	65.0	66.6	8.9	8.5	8.7
22	63	47	60	69.2	66.4	67.7	8.8	8.4	8.6
23	62	59	60	69.7	66.7	68.3	8.8	8.4	8.6
24	62	59	60	70.5	67.2	68.9	8.8	8.4	8.5
25	60	58	59	70.2	67.3	68.8	8.8	8.4	8.6
26	61	58	59	70.0	67.0	68.6	8.8	8.4	8.6
27	66	61	64	71.0	67.3	69.1	8.4	8.1	8.3
28	80	64	67	72.2	68.6	70.3	8.4	8.0	8.2
29	67	62	64	72.0	68.6	70.4	8.5	8.0	8.3
30	68	61	63	71.7	68.7	70.1	8.6	8.2	8.4
31	64	61	62	71.0	68.1	69.6	8.7	8.2	8.4

Comments:

0 reading indicates that the station was out of service.