



Ripon on the Stanislaus River Water Quality

Period: August 2022 Run Date: 11/22/2022

Electrical Conductivity, UMHOS				WATER TEMPERATURE, DEG			DISSOLVED OXYZEN, PPM		
Day	High	Low	Mean	High	Low	Mean	High	Low	Mean
1	82	71	74	77.6	74.7	76.0	8.6	7.4	8.0
2	72	71	72	80.0	72.8	76.2	8.8	7.7	8.1
3	72	19	67	80.8	74.0	77.3	8.7	7.5	8.0
4	82	69	70	81.6	75.8	78.6	8.6	7.3	7.8
5	73	68	69	78.1	75.0	76.5	8.8	7.4	8.0
6	83	69	72	77.9	71.4	74.6	9.1	7.8	8.3
7	76	68	70	79.0	71.9	75.2	9.0	7.7	8.2
8	81	68	69	77.9	72.0	74.7	9.1	7.7	8.3
9	74	68	70	77.5	71.8	74.7	9.1	7.8	8.4
10	76	69	70	78.2	71.1	74.6	9.2	7.8	8.4
11	69	68	69	79.2	72.2	75.4	9.0	7.7	8.2
12	80	68	71	79.0	71.8	75.1	9.0	7.7	8.2
13	75	69	70	79.0	71.6	75.0	9.1	7.7	8.2
14	81	69	70	78.6	71.4	74.9	9.1	7.7	8.2
15	77	69	70	79.2	72.0	75.5	9.1	7.7	8.2
16	73	69	70	80.1	73.2	76.5	9.0	7.5	8.1
17	81	69	71	76.8	74.2	75.6	8.7	7.4	8.0
18	81	69	71	79.3	71.9	75.3	9.1	7.7	8.2
19	87	69	71	79.3	72.3	75.6	9.1	7.6	8.2
20	70	68	69	79.8	72.7	76.0	9.0	7.6	8.1
21	81	69	70	79.7	73.6	76.4	9.0	7.5	8.1
22	81	69	70	79.1	72.6	75.8	9.0	7.6	8.2
23	73	68	69	80.0	73.1	76.4	8.9	7.6	8.1
24	86	69	74	80.7	74.2	77.3	8.9	7.4	8.0
25	81	69	72	80.3	74.1	77.1	9.0	7.4	8.0
26	103	69	77	79.3	73.2	76.3	9.2	7.5	8.1
27	99	70	80	79.8	73.2	76.3	9.2	7.5	8.1
28	70	68	69	78.4	72.4	75.3	9.3	7.6	8.2
29	83	69	71	78.1	72.1	75.2	9.3	7.7	8.4
30	75	69	70	78.8	71.8	75.1	9.3	7.7	8.3
31	74	68	69	78.4	72.0	75.0	9.3	7.7	8.3

COMMENT(S):

0 reading indicates that the station was out of service.