

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

SEPTEMBER 2009

WATER QUALITY REPORT

RUN DATE: October 2, 2009

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	80	67	71	75.5	70.0	72.6	8.1	7.6	7.8
2	73	67	69	74.6	70.9	72.7	8.3	7.5	7.9
3	77	69	71	76.5	70.2	73.0	8.1	7.5	7.8
4	74	70	71	76.1	70.7	73.0	8.2	7.5	7.8
5	82	71	73	74.5	68.5	71.3	8.4	7.7	8.0
6	77	69	71	73.7	69.0	71.2	8.4	7.8	8.1
7	78	64	69	73.1	68.2	70.4	8.5	7.9	8.1
8	80	67	70	72.7	67.5	69.9	8.5	7.9	8.1
9	79	69	70	73.0	67.8	70.2	8.5	7.9	8.2
10	81	70	72	73.3	68.6	70.7	8.5	7.8	8.1
11	84	70	73	73.8	68.7	71.1	8.4	7.7	8.0
12	81	61	69	71.8	68.0	70.4	8.2	7.6	7.9
13	61	55	57	67.5	62.6	64.2	9.2	8.1	8.9
14	85	54	59	64.5	61.8	63.4	9.3	8.5	9.0
15	57	55	56	64.9	61.7	63.4	9.3	8.7	9.0
16	56	54	55	64.8	61.5	63.3	9.6	9.0	9.3
17	59	55	56	65.3	62.0	63.8	9.4	8.9	9.1
18	57	54	56	65.7	62.6	64.3	9.3	8.8	9.1
19	60	55	57	65.7	63.1	64.5	9.3	8.8	9.1
20	61	55	57	65.6	62.7	64.3	9.4	8.9	9.1
21	69	55	57	65.4	62.3	64.1	9.5	9.0	9.3
22	71	56	58	65.5	62.3	64.0	9.5	9.1	9.3
23	73	56	59	65.2	62.1	63.8	9.6	9.1	9.3
24	72	56	59	65.0	61.8	63.6	9.6	9.2	9.4
25	67	56	58	64.6	61.5	63.2	9.7	9.3	9.5
26	69	55	58	64.5	61.3	63.0	9.8	9.3	9.6
27	61	56	58	64.5	61.8	63.3	9.8	9.3	9.5
28	65	56	58	63.9	61.8	63.1	9.7	9.3	9.5
29	63	56	57	62.9	60.3	61.4	10.0	9.4	9.8
30	62	55	57	60.2	57.9	59.2	10.7	10.0	10.5

Comments:

0 reading indicates that the station was out of service.