

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

SEPTEMBER 2013

WATER QUALITY REPORT

RUN DATE: February 20, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	105	86	92	77.3	72.9	75.0	7.9	7.4	7.6
2	101	86	91	75.8	73.2	74.3	8.0	7.5	7.7
3	90	78	83	75.8	71.8	73.5	8.1	7.6	7.8
4	103	79	87	75.1	70.7	72.8	8.2	7.6	7.9
5	102	87	95	74.7	70.2	72.3	8.2	7.7	7.9
6	104	89	94	74.6	69.8	72.1	8.3	7.7	8.0
7	90	85	87	75.5	70.0	72.7	8.3	7.7	7.9
8	89	83	86	75.5	70.8	73.1	8.2	7.7	7.9
9	107	88	93	75.5	71.3	73.2	8.2	7.7	7.9
10	105	93	97	75.3	71.2	73.3	8.2	7.6	7.9
11	102	85	92	74.5	70.6	72.3	8.2	7.7	7.9
12	90	84	86	74.1	69.6	71.6	8.4	7.8	8.1
13	96	84	87	74.4	70.2	72.1	8.4	7.8	8.0
14	103	93	95	74.3	70.0	72.0	8.3	7.8	8.0
15	102	94	96	73.3	69.0	71.2	8.4	7.8	8.0
16	101	90	94	73.4	69.1	71.2	8.4	7.8	8.1
17	93	88	89	72.2	68.3	70.2	8.5	7.9	8.2
18	97	91	94	71.2	67.3	69.3	8.7	8.1	8.3
19	97	90	92	71.1	66.5	68.8	8.7	8.1	8.4
20	98	91	94	70.6	66.7	68.6	8.7	8.1	8.4
21	113	90	96	68.3	66.1	67.5	8.7	8.2	8.4
22	97	90	93	66.7	64.0	65.4	8.5	8.2	8.4
23	96	88	92	67.8	63.5	65.6	8.9	8.2	8.5
24	89	87	88	69.5	64.9	66.9	8.7	8.2	8.5
25	98	88	92	67.5	64.4	66.0	8.8	8.3	8.5
26	99	92	95	66.8	63.1	64.9	9.0	8.2	8.6
27	96	92	94	65.4	61.4	63.6	9.3	8.7	8.9
28	98	90	94	65.5	61.3	63.5	9.3	8.8	9.0
29	96	89	93	66.2	62.6	64.4	9.3	8.7	8.9
30	89	87	88	67.7	63.7	65.5	9.1	8.5	8.8

Comments:

0 reading indicates that the station was out of service.