

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

SEPTEMBER 2014

WATER QUALITY REPORT

RUN DATE: October 1, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	100	90	94	80.5	74.0	77.0	8.1	7.4	7.7
2	114	78	89	81.0	74.2	77.4	8.2	7.4	7.7
3	117	83	92	79.7	73.4	76.6	8.3	7.5	7.8
4	112	81	93	79.7	73.2	76.5	8.4	7.5	7.9
5	109	81	89	79.4	73.2	76.4	8.5	7.5	7.9
6	105	81	90	79.4	72.9	76.1	8.5	7.6	7.9
7	105	83	89	78.6	72.1	75.5	8.6	7.6	8.0
8	102	83	87	77.8	71.9	74.8	8.6	7.7	8.0
9	91	80	86	76.7	70.0	73.5	8.8	7.8	8.1
10	99	81	87	77.7	70.9	74.2	8.7	7.8	8.1
11	87	80	83	78.4	71.4	74.9	8.7	7.7	8.0
12	90	82	87	78.9	71.9	75.5	8.6	7.6	8.0
13	115	84	92	78.2	72.9	75.7	8.4	7.6	7.9
14	118	86	96	79.4	72.7	76.2	8.4	7.5	7.9
15	125	88	102	79.2	73.2	76.2	8.4	7.5	7.8
16	128	85	95	78.0	72.3	75.2	8.6	7.6	7.9
17	113	84	92	78.4	72.3	75.2	8.5	7.6	7.9
18	103	85	93	78.7	72.6	75.3	8.3	7.3	7.7
19	104	85	91	78.1	71.8	74.9	8.0	7.2	7.5
20	108	80	88	77.4	72.1	74.8	8.6	7.3	7.8
21	128	86	100	77.0	72.0	74.5	8.7	7.5	7.9
22	123	84	97	76.5	71.4	73.9	8.8	7.7	8.0
23	125	83	95	77.0	71.5	74.2	8.8	7.7	8.0
24	141	84	95	77.4	71.9	74.5	8.7	7.6	8.0
25	169	84	95	74.7	71.5	72.8	8.4	7.5	7.8
26	103	1	85	72.4	68.2	70.4	8.6	7.4	8.1
27	111	82	91	72.6	67.4	70.0	8.9	7.8	8.3
28	105	82	91	70.4	68.1	69.4	8.9	8.0	8.4
29	109	82	94	71.8	66.1	69.0	9.2	8.1	8.5
30	119	81	94	72.3	67.2	69.8	9.1	8.1	8.4

Comments:

0 reading indicates that the station was out of service.