

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

SEPTEMBER 2018

WATER QUALITY REPORT

RUN DATE: October 4, 2018

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	76	65	70	73.3	68.5	70.6	8.9	8.4	8.6
2	71	67	69	73.4	69.0	71.0	8.9	8.3	8.5
3	73	68	70	73.5	69.3	71.2	8.9	8.2	8.5
4	80	67	71	73.3	68.7	71.0	8.9	8.2	8.5
5	82	67	72	73.2	68.8	71.0	8.9	8.3	8.5
6	74	67	69	72.8	68.5	70.5	9.0	8.3	8.6
7	70	58	64	73.0	68.1	70.5	8.9	8.3	8.6
8	75	59	64	73.1	68.7	70.8	8.8	8.2	8.4
9	64	60	61	72.2	67.6	69.9	8.9	8.3	8.5
10	64	60	62	71.6	67.6	69.5	9.0	8.3	8.6
11	65	59	62	71.7	67.1	69.3	9.0	8.4	8.6
12	66	58	60	69.4	66.2	67.6	9.2	8.4	8.8
13	63	58	60	68.4	64.7	66.4	9.3	8.7	9.0
14	62	58	60	68.1	64.3	66.1	9.4	8.8	9.0
15	64	58	60	68.0	64.2	66.0	9.4	8.7	9.0
16	71	59	64	67.3	63.7	65.5	9.4	8.8	9.0
17	69	59	63	67.9	63.8	65.8	9.4	8.8	9.0
18	64	59	60	67.9	63.7	65.7	9.4	8.8	9.0
19	70	59	62	68.0	63.7	65.9	9.4	8.7	9.0
20	64	59	60	68.3	64.1	66.1	9.4	8.7	9.0
21	66	55	60	68.9	64.4	66.7	9.3	8.6	8.9
22	62	55	58	69.0	64.7	67.0	9.3	8.6	8.9
23	67	55	57	69.0	65.2	67.0	9.2	8.6	8.8
24	72	56	62	69.0	64.5	66.8	9.3	8.6	8.8
25	70	56	62	68.3	64.7	66.6	9.3	8.6	8.9
26	60	55	56	68.1	64.1	66.2	9.4	8.7	9.0
27	62	56	58	68.8	64.5	66.6	9.4	8.7	8.9
28	64	56	59	68.0	64.7	66.4	9.4	8.7	8.9
29	61	56	58	67.5	63.8	65.8	9.4	8.7	9.0
30	59	56	58	67.0	63.7	65.4	9.4	8.8	9.1

Comments:

0 reading indicates that the station was out of service.