

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**

**SEPTEMBER 2019**

**WATER QUALITY REPORT**

RUN DATE: October 8, 2019

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	65	60	61	70.7	68.1	69.4	8.8	8.3	8.5
2	65	59	61	70.7	68.2	69.3	8.8	8.3	8.6
3	63	61	62	70.7	67.7	69.1	8.8	8.3	8.5
4	63	62	62	70.9	67.6	69.3	8.7	8.3	8.5
5	66	62	63	71.0	68.1	69.4	8.7	8.3	8.5
6	65	61	62	70.4	67.3	68.8	8.9	8.4	8.6
7	71	61	63	68.5	66.9	67.7	9.0	8.5	8.7
8	64	61	62	67.9	65.1	66.4	9.1	8.7	8.9
9	63	61	62	67.6	64.7	66.2	9.1	8.7	8.9
10	66	62	63	67.3	64.9	66.1	9.1	8.7	8.9
11	64	63	64	67.7	64.9	66.4	9.2	8.7	8.9
12	67	62	63	68.1	65.0	66.7	9.2	8.7	8.9
13	68	63	65	68.7	65.7	67.2	9.1	8.6	8.8
14	66	63	65	69.0	65.8	67.2	9.1	8.6	8.8
15	67	63	64	68.3	66.0	67.0	9.1	8.5	8.8
16	73	62	65	67.1	65.1	66.1	9.0	8.7	8.8
17	69	55	62	65.7	63.1	64.5	9.4	8.6	9.0
18	58	56	57	65.2	62.8	64.1	9.4	9.0	9.2
19	58	56	56	65.7	63.1	64.3	9.4	9.0	9.2
20	58	55	57	65.5	62.8	64.2	9.4	9.0	9.2
21	59	56	58	65.6	62.5	64.1	9.5	9.0	9.2
22	76	56	61	66.1	63.4	64.6	9.4	9.0	9.2
23	59	56	57	66.3	63.8	65.0	9.4	9.0	9.2
24	61	58	60	66.9	63.7	65.3	9.3	8.9	9.1
25	65	58	60	67.4	64.7	66.1	9.2	8.8	9.0
26	59	56	57	68.1	65.2	66.6	9.2	8.8	8.9
27	60	57	57	67.4	65.1	66.2	9.2	8.8	9.0
28	59	57	57	65.7	63.4	64.6	9.3	8.9	9.1
29	59	57	57	63.4	61.1	62.3	9.6	9.0	9.3
30	58	55	57	62.4	59.5	60.8	9.8	9.4	9.6

Comments:

0 reading indicates that the station was out of service.