

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**

**WATER QUALITY REPORT**

**OCTOBER 2011**

RUN DATE: November 9, 2011

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	66	66	66	59.0	57.9	58.4	9.4	9.3	9.4
2	70	66	69	58.3	57.0	57.5	9.6	9.4	9.5
3	68	66	67	57.2	56.3	56.7	9.7	9.5	9.6
4	66	66	66	56.6	56.0	56.2	9.7	9.5	9.6
5	73	66	71	56.9	56.0	56.4	9.6	9.0	9.3
6	72	70	71	56.0	54.7	55.3	9.5	9.1	9.3
7	70	68	69	55.5	54.2	54.8	9.7	9.6	9.7
8	71	68	69	56.1	55.0	55.4	9.8	9.6	9.7
9	69	68	68	56.3	55.1	55.7	9.8	9.6	9.7
10	71	68	70	56.3	55.6	55.9	9.7	9.5	9.6
11	68	67	68	57.0	55.3	56.1	9.7	9.5	9.6
12	76	67	70	57.8	56.7	57.1	9.6	9.2	9.4
13	75	68	71	56.8	55.3	55.9	9.7	9.3	9.6
14	72	68	69	56.7	55.3	55.9	9.8	9.4	9.6
15	73	70	72	56.3	55.2	55.8	9.7	9.4	9.6
16	72	70	71	57.3	55.8	56.5	9.7	9.3	9.6
17	71	70	71	57.0	55.8	56.3	9.7	9.4	9.7
18	76	70	73	57.7	56.0	56.8	9.8	9.4	9.6
19	75	69	71	56.9	55.7	56.3	9.7	9.5	9.6
20	71	68	69	57.4	56.0	56.6	9.7	9.4	9.5
21	74	71	72	56.6	55.4	55.9	9.7	9.5	9.7
22	71	67	69	57.1	55.7	56.3	9.8	9.4	9.6
23	71	68	69	56.4	55.1	55.7	9.8	9.5	9.7
24	74	68	71	57.2	55.7	56.4	9.8	9.4	9.6
25	74	68	70	57.0	55.7	56.5	9.7	9.5	9.6
26	73	68	70	57.0	56.1	56.6	9.6	9.5	9.6
27	73	70	71	56.1	54.7	55.5	9.7	9.6	9.7
28	75	71	73	56.3	55.1	55.6	9.8	9.7	9.7
29	74	73	73	55.9	55.0	55.4	9.8	9.7	9.7
30	76	72	74	56.0	55.1	55.5	9.8	9.7	9.8
31	74	72	73	56.0	55.1	55.5	9.8	9.7	9.8

Comments:

0 reading indicates that the station was out of service.