

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**

**WATER QUALITY REPORT**

**OCTOBER 2014**

RUN DATE: November 3, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	95	83	87	71.9	67.2	69.5	9.1	8.1	8.4
2	87	73	79	71.6	67.2	69.3	9.1	8.1	8.4
3	83	75	78	72.1	67.5	69.6	9.0	8.2	8.5
4	83	76	80	72.1	67.4	69.6	9.0	8.2	8.4
5	81	75	78	72.2	67.5	69.7	9.0	8.2	8.4
6	84	77	79	72.3	67.8	69.9	8.9	8.1	8.4
7	118	76	97	73.1	68.2	70.5	8.1	7.1	7.6
8	152	92	108	72.8	68.8	70.7	7.7	7.1	7.4
9	102	90	95	72.0	68.0	70.0	8.1	7.4	7.7
10	104	96	99	70.9	67.1	69.1	8.1	7.6	7.8
11	100	94	97	70.8	66.6	68.6	8.2	7.7	7.9
12	99	90	93	70.2	66.5	68.3	8.3	7.8	7.9
13	93	82	86	69.5	65.1	67.3	8.7	7.9	8.3
14	90	83	86	69.0	65.3	67.2	8.7	8.2	8.4
15	90	83	85	68.8	65.9	67.3	8.8	8.3	8.4
16	90	83	86	68.1	64.8	66.5	9.0	8.3	8.6
17	89	83	86	67.1	63.9	65.5	9.1	8.5	8.7
18	90	83	86	67.3	63.5	65.3	9.2	8.6	8.8
19	88	83	85	67.1	63.3	65.2	9.2	8.6	8.9
20	90	83	86	67.4	64.1	65.6	9.2	8.6	8.9
21	97	82	86	65.8	63.2	64.5	9.4	8.6	9.0
22	84	72	79	64.3	62.3	63.3	9.2	8.9	9.1
23	76	71	73	64.0	61.8	63.0	9.3	9.1	9.2
24	78	69	73	64.9	62.1	63.5	9.2	8.8	9.1
25	81	65	73	63.8	62.7	63.1	9.2	8.8	9.0
26	66	64	65	62.7	61.7	62.2	9.2	9.0	9.1
27	67	64	65	61.9	60.8	61.4	9.4	9.2	9.3
28	67	65	66	61.8	60.0	60.9	9.5	9.4	9.4
29	68	66	67	62.4	60.3	61.4	9.5	9.3	9.4
30	72	67	69	62.9	61.2	62.1	9.4	9.2	9.3
31	85	68	72	63.5	61.8	62.5	9.2	8.9	9.1

Comments:

0 reading indicates that the station was out of service.