

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**  
**WATER QUALITY REPORT**

**OCTOBER 2017**

RUN DATE: November 14, 2017

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	65	61	62	63.5	61.3	62.4	9.8	8.9	9.3
2	64	61	62	62.1	59.5	60.8	9.8	9.0	9.4
3	62	61	61	60.3	57.7	59.1	10.1	9.2	9.6
4	62	61	61	59.9	56.8	58.3	10.3	9.5	9.8
5	63	61	62	60.0	56.7	58.4	10.2	9.6	9.8
6	63	61	62	60.2	57.0	58.7	10.2	9.5	9.8
7	61	53	56	58.7	56.2	57.4	10.1	9.6	9.9
8	56	53	54	57.1	55.4	56.2	10.2	10.0	10.1
9	55	53	54	57.1	55.1	56.1	10.2	10.0	10.1
10	55	54	55	56.8	54.7	55.8	10.3	10.1	10.2
11	56	55	55	56.6	55.0	55.8	10.2	10.1	10.2
12	57	55	57	55.9	54.1	55.1	10.3	10.1	10.2
13	58	57	58	55.3	53.1	54.3	10.4	10.2	10.3
14	60	58	59	55.8	53.5	54.8	10.4	10.1	10.3
15	58	56	57	55.5	53.2	54.6	10.6	10.2	10.5
16	58	56	57	56.0	53.8	54.9	10.5	10.3	10.4
17	59	57	58	56.0	54.2	55.2	10.4	10.2	10.3
18	65	58	62	56.4	54.2	55.4	10.3	10.2	10.3
19	65	64	64	55.7	54.3	54.9	0.0	0.0	0.0
20	63	60	61	56.8	55.8	56.4	9.9	9.5	9.8
21	60	57	59	57.3	55.6	56.5	9.9	9.7	9.8
22	59	53	55	56.3	54.2	55.3	10.3	9.9	10.2
23	55	53	54	55.8	54.2	55.0	10.4	10.2	10.3
24	54	53	53	56.0	54.5	55.2	10.4	10.1	10.3
25	56	53	54	56.4	54.9	55.6	10.3	10.0	10.1
26	55	54	55	56.7	55.2	55.9	10.1	9.9	10.0
27	56	54	55	57.0	55.2	56.1	10.0	9.8	9.9
28	55	53	53	55.9	54.8	55.3	10.3	10.1	10.2
29	53	53	53	55.3	54.4	54.8	10.3	10.1	10.2
30	53	53	53	55.1	54.0	54.5	10.4	10.2	10.2
31	54	53	53	54.6	53.5	54.1	10.4	10.2	10.3

Comments:

0 reading indicates that the station was out of service.