

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**

**WATER QUALITY REPORT**

**NOVEMBER 2014**

RUN DATE: December 1, 2014

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	73	67	69	63.0	61.5	62.1	9.1	8.9	9.0
2	68	67	68	61.3	60.3	60.8	9.3	8.8	9.1
3	69	67	68	60.4	59.1	59.8	9.6	9.4	9.6
4	69	68	68	60.4	58.7	59.6	9.7	9.6	9.7
5	70	68	69	61.1	59.2	60.2	9.7	9.5	9.6
6	71	65	67	61.6	59.8	60.8	9.5	9.2	9.4
7	68	64	66	62.0	60.3	61.2	9.2	9.1	9.2
8	71	66	68	62.1	60.3	61.3	9.2	9.1	9.1
9	75	68	71	62.4	60.4	61.4	9.1	8.9	9.0
10	79	73	75	62.3	60.0	61.2	9.0	8.9	8.9
11	81	75	77	61.4	59.9	60.7	9.1	8.9	9.0
12	82	76	79	62.1	59.9	61.0	9.2	8.9	9.0
13	102	78	82	62.4	61.1	61.7	9.0	8.7	8.9
14	83	77	80	62.3	60.3	61.3	9.2	8.6	8.9
15	82	77	80	61.1	59.3	60.2	9.5	8.9	9.2
16	80	76	77	59.5	57.6	58.5	9.8	9.3	9.5
17	82	76	79	57.5	55.5	56.6	10.2	9.6	9.9
18	84	76	79	56.6	54.7	55.8	10.4	9.9	10.1
19	82	76	78	57.2	55.7	56.4	10.2	9.8	10.0
20	85	75	78	58.0	57.0	57.3	9.9	9.6	9.8
21	82	76	78	58.3	57.0	57.6	10.1	9.6	9.8
22	83	76	80	58.0	57.1	57.5	9.9	9.6	9.7
23	80	75	77	57.8	56.0	56.9	10.3	9.7	9.9
24	83	76	78	56.3	54.4	55.5	10.5	9.8	10.1
25	84	74	79	55.8	53.7	54.7	10.7	10.1	10.4
26	82	75	78	55.4	53.0	54.3	10.8	10.2	10.4
27	80	74	77	55.9	53.5	54.7	10.8	10.2	10.4
28	81	75	77	55.5	53.4	54.4	10.8	10.1	10.4
29	91	74	78	56.1	54.2	55.3	10.3	9.8	10.1
30	78	70	74	57.3	55.4	56.0	9.9	9.6	9.8

Comments:

0 reading indicates that the station was out of service.