

UNITED STATES DEPARTMENT OF THE INTERIOR
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

NOVEMBER 2015

WATER QUALITY REPORT

RUN DATE: December 11, 2015

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	71	69	69	65.5	63.5	64.6	8.8	8.5	8.7
2	76	67	72	65.3	63.8	64.6	8.6	8.2	8.4
3	78	73	76	63.7	62.3	63.0	8.7	8.2	8.5
4	77	73	75	62.2	60.5	61.1	9.1	8.7	8.9
5	74	72	73	60.3	58.8	59.6	9.4	9.1	9.3
6	74	72	73	59.6	58.3	59.1	9.5	9.4	9.4
7	75	73	74	59.4	57.8	58.7	9.5	9.4	9.5
8	82	73	75	59.6	57.7	58.6	9.5	9.3	9.4
9	77	73	75	59.0	58.0	58.5	9.3	9.2	9.3
10	85	79	82	58.0	56.9	57.5	9.4	9.1	9.2
11	89	85	87	57.3	55.2	56.3	9.8	9.4	9.6
12	88	84	86	56.4	54.5	55.5	10.1	9.6	9.8
13	86	82	84	56.2	53.8	55.0	10.2	9.9	10.0
14	85	81	83	56.3	53.8	55.1	10.3	9.9	10.1
15	84	81	82	55.8	54.1	54.9	10.2	10.0	10.1
16	85	81	82	53.9	52.3	53.2	10.5	10.0	10.3
17	84	80	82	53.3	51.2	52.3	10.9	10.4	10.6
18	84	80	82	53.6	51.2	52.4	10.9	10.5	10.7
19	85	80	82	54.5	52.0	53.2	10.8	10.3	10.5
20	84	81	82	55.5	53.1	54.3	10.6	10.2	10.4
21	84	81	83	56.3	53.9	55.1	10.5	10.1	10.3
22	84	81	82	56.2	53.9	55.1	10.5	10.1	10.2
23	84	81	82	56.6	54.4	55.4	10.4	10.0	10.2
24	90	81	83	56.1	53.9	54.7	10.4	10.0	10.1
25	85	82	83	54.4	52.6	53.6	10.4	10.1	10.2
26	87	81	83	52.4	50.1	51.2	11.0	10.3	10.7
27	85	81	83	49.8	48.3	49.2	11.4	10.8	11.1
28	85	81	83	48.5	46.8	47.8	11.7	11.2	11.4
29	84	81	82	47.8	45.7	46.9	11.9	11.4	11.6
30	83	80	81	47.7	45.7	46.7	11.9	11.6	11.7

Comments:

0 reading indicates that the station was out of service.