

UNITED STATES DEPARTMENT OF THE INTERIOR  
 U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

**RIPON ON THE STANISLAUS RIVER**  
**WATER QUALITY REPORT**

**NOVEMBER 2019**

RUN DATE: December 11, 2019

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	57	55	56	53.9	52.5	53.1	10.8	10.6	10.7
2	57	55	56	54.0	52.7	53.4	10.7	10.5	10.6
3	56	56	56	54.1	52.8	53.4	10.6	10.5	10.5
4	59	56	58	54.5	52.9	53.8	10.5	10.3	10.4
5	63	59	61	54.9	53.2	54.1	10.3	9.9	10.1
6	65	63	64	55.3	53.9	54.6	10.1	9.9	10.0
7	79	63	66	56.3	54.3	55.0	10.1	9.9	10.0
8	65	62	64	55.8	53.9	54.8	10.1	9.9	10.0
9	68	62	65	56.3	53.4	54.8	10.3	9.9	10.1
10	73	67	70	55.6	53.3	54.5	9.9	8.6	9.5
11	71	66	68	56.0	53.3	54.7	9.5	8.5	9.2
12	69	58	62	56.0	54.0	55.0	10.1	8.9	9.8
13	60	58	59	55.6	54.2	54.8	10.3	10.1	10.2
14	60	59	60	55.6	54.5	55.0	10.3	10.2	10.2
15	60	59	60	56.0	54.6	55.3	10.3	10.1	10.2
16	61	60	60	55.6	54.2	54.9	10.3	10.2	10.3
17	60	60	60	55.2	53.7	54.4	10.4	10.3	10.4
18	61	60	60	55.1	53.6	54.3	10.4	10.3	10.4
19	61	60	60	55.1	53.6	54.3	10.4	10.2	10.3
20	61	60	61	54.6	53.5	54.0	10.3	10.2	10.2
21	61	60	61	54.2	52.9	53.5	10.5	10.3	10.4
22	62	60	61	53.6	52.3	52.9	10.7	10.4	10.6
23	61	60	61	53.1	51.7	52.4	10.8	10.6	10.7
24	61	60	61	52.5	51.1	51.8	10.9	10.7	10.8
25	62	60	61	51.7	50.6	51.2	10.9	10.7	10.8
26	66	59	61	50.5	49.3	49.8	11.0	10.8	10.9
27	67	60	63	50.4	49.1	49.7	10.8	10.4	10.6
28	61	59	60	50.3	49.5	49.9	10.7	10.5	10.6
29	63	59	60	51.2	49.5	50.2	10.9	10.6	10.7
30	60	59	60	50.3	49.6	49.9	10.8	10.7	10.7

Comments:

0 reading indicates that the station was out of service.