



Ripon on the Stanislaus River Water Quality

Period: November 2023 Run Date: 12/8/2023

Day	Electrical Conductivity, UMHOS			WATER TEMPERATURE, DEG			DISSOLVED OXYZEN, PPM		
	High	Low	Mean	High	Low	Mean	High	Low	Mean
1	81	66	69	54.6	52.4	53.5	10.5	10.2	10.3
2	73	69	71	55.2	53.0	54.2	10.2	10.0	10.1
3	78	72	74	56.6	54.0	55.3	10.0	9.6	9.8
4	78	77	77	57.6	55.3	56.5	9.9	9.5	9.6
5	77	76	77	58.7	56.8	57.7	9.8	9.4	9.6
6	90	76	78	59.3	58.2	58.7	9.6	9.3	9.4
7	78	76	77	58.8	57.0	57.9	9.8	9.3	9.5
8	78	76	77	57.0	55.2	56.2	10.0	9.6	9.8
9	77	76	77	55.1	53.5	54.4	10.5	9.9	10.2
10	77	75	76	54.2	52.1	53.2	10.6	10.2	10.4
11	77	73	75	54.0	51.6	52.8	10.8	10.4	10.5
12	77	73	75	54.4	52.2	53.3	10.7	10.3	10.5
13	85	76	80	54.5	52.3	53.5	10.6	10.2	10.4
14	82	76	79	54.5	52.2	53.4	10.6	10.2	10.4
15	77	74	75	53.6	52.6	53.2	10.6	10.3	10.4
16	77	73	75	55.6	53.1	54.4	10.5	10.1	10.3
17	77	74	75	55.6	54.1	55.0	10.4	10.0	10.2
18	90	76	79	58.3	55.3	56.5	10.1	9.5	9.8
19	77	75	76	56.5	54.7	55.7	10.0	9.6	9.7
20	86	76	81	54.6	53.0	53.9	9.9	9.3	9.6
21	81	78	80	53.3	51.5	52.4	10.6	9.9	10.3
22	79	76	77	52.5	50.6	51.8	10.8	10.4	10.6
23	79	77	78	53.0	50.9	52.0	10.7	10.3	10.5
24	78	76	77	51.6	50.1	50.9	10.8	10.3	10.5
25	79	77	78	50.1	48.7	49.4	11.1	10.6	10.9
26	79	77	78	48.9	47.1	48.0	11.4	10.9	11.2
27	79	77	78	48.4	46.3	47.4	11.5	11.1	11.3
28	79	77	78	48.2	46.1	47.2	11.6	11.2	11.3
29	80	77	78	49.2	47.0	48.1	11.4	11.0	11.2
30	81	79	80	49.8	47.8	48.9	11.3	10.8	11.1

COMMENT(S):

0 reading indicates that the station was out of service.