

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

DECEMBER 2015

WATER QUALITY REPORT

RUN DATE: January 5, 2016

ELECTRICAL CONDUCTIVITY, UMHOS

WATER TEMPERATURE, DEG

DISSOLVED OXYZEN, PPM

DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	83	79	81	48.7	46.2	47.5	11.9	11.5	11.6
2	84	80	82	50.0	47.6	48.7	11.8	11.3	11.5
3	92	81	84	51.9	49.0	49.9	11.3	10.8	11.1
4	85	82	84	51.6	49.1	50.4	11.1	10.8	10.9
5	85	82	84	51.1	49.3	50.3	11.4	10.8	11.0
6	86	84	85	52.9	50.4	51.6	11.2	10.7	10.9
7	86	83	84	54.2	52.1	53.0	11.0	10.5	10.7
8	86	84	85	54.6	52.8	53.7	10.8	10.3	10.5
9	87	84	85	56.8	54.7	55.7	10.6	10.0	10.2
10	91	85	88	56.0	55.2	55.5	10.0	9.6	9.7
11	93	77	83	55.5	53.8	54.7	10.1	9.6	9.8
12	97	78	86	53.6	51.6	52.7	10.5	9.7	10.0
13	94	82	89	53.4	51.3	52.5	10.1	9.8	10.0
14	86	82	84	51.1	49.1	50.1	10.6	10.0	10.3
15	84	79	81	48.9	47.1	48.0	11.3	10.5	10.9
16	84	79	82	47.0	45.2	46.3	11.8	11.1	11.4
17	82	77	79	47.3	45.2	46.3	12.0	11.4	11.6
18	80	76	78	48.0	45.6	46.8	11.9	11.3	11.6
19	81	76	79	50.7	48.0	49.6	11.4	10.8	11.1
20	84	75	79	50.0	48.6	49.5	11.4	10.7	10.9
21	87	77	84	51.7	49.9	50.5	10.9	10.4	10.7
22	81	74	78	54.3	51.3	52.9	10.8	10.2	10.4
23	105	82	94	53.7	52.1	53.2	10.0	9.2	9.5
24	97	90	92	52.0	50.1	51.1	9.8	9.3	9.5
25	93	89	91	49.9	48.1	48.8	10.6	9.8	10.3
26	101	92	96	47.9	45.9	46.9	11.2	10.3	10.8
27	93	89	91	46.0	44.4	45.5	11.6	11.1	11.4
28	90	85	87	47.3	45.8	46.3	11.5	11.2	11.3
29	88	84	86	46.2	44.5	45.5	11.8	11.2	11.5
30	89	85	87	46.3	43.9	45.2	11.7	11.5	11.6
31	91	86	88	46.5	44.6	45.6	11.9	11.5	11.7

Comments:

0 reading indicates that the station was out of service.