

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

RIPON ON THE STANISLAUS RIVER

DECEMBER 2020

WATER QUALITY REPORT

RUN DATE: February 2, 2021

ELECTRICAL CONDUCTIVITY, UMHOS				WATER TEMPERATURE, DEG			DISSOLVED OXYGEN, PPM		
DAY	HIGH	LOW	MEAN	HIGH	LOW	MEAN	HIGH	LOW	MEAN
1	72	70	70	48.6	46.4	47.6	11.2	10.8	10.9
2	78	70	72	49.1	46.3	47.5	11.2	10.8	11.0
3	74	71	72	49.0	46.7	47.9	11.1	10.8	10.9
4	80	56	71	50.1	47.3	48.4	11.3	10.8	11.0
5	73	70	71	49.2	46.9	48.1	11.4	10.9	11.1
6	74	70	72	49.3	47.2	48.3	11.4	10.9	11.1
7	72	69	71	49.2	47.0	48.2	11.3	10.9	11.1
8	76	70	72	48.9	46.9	48.0	11.3	10.8	11.0
9	78	74	76	48.4	46.7	47.7	11.4	10.9	11.1
10	98	76	81	50.7	46.7	48.0	11.3	10.7	11.0
11	102	75	79	50.9	46.3	47.8	11.5	10.3	11.1
12	114	75	82	51.3	49.0	50.1	10.5	9.6	10.2
13	95	75	81	53.4	50.1	51.8	9.9	7.9	9.3
14	78	60	68	52.2	49.9	50.9	9.8	8.0	9.1
15	88	64	82	51.0	48.3	49.5	10.3	8.1	9.5
16	79	69	75	49.8	47.9	49.0	10.9	10.2	10.5
17	88	74	78	51.2	49.2	50.3	10.6	9.9	10.4
18	75	66	73	50.1	48.5	49.3	10.9	10.2	10.5
19	83	66	78	49.3	47.5	48.4	10.9	9.5	10.4
20	80	75	76	49.1	47.2	48.2	11.3	10.7	11.0
21	76	63	72	48.7	48.1	48.4	11.0	10.6	10.8
22	76	73	74	49.0	47.6	48.3	11.2	10.6	10.9
23	76	74	75	48.6	47.1	47.8	11.5	10.9	11.2
24	77	74	76	49.0	47.9	48.3	11.4	10.9	11.1
25	80	76	79	48.9	47.5	48.3	11.5	10.8	11.1
26	81	78	80	51.1	48.8	49.8	11.0	10.5	10.8
27	80	78	79	51.1	49.2	50.1	11.1	10.4	10.7
28	80	75	77	51.0	49.5	50.1	11.1	10.3	10.7
29	76	74	75	49.6	47.9	48.8	11.3	10.5	10.9
30	76	73	74	48.6	46.7	47.8	11.6	10.9	11.2
31	84	73	77	49.8	48.1	48.9	11.4	10.8	11.0

Comments:

0 reading indicates that the station was out of service.