

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

VICTORIA CANAL ON THE MIDDLE RIVER
WATER QUALITY REPORT

MAY 2006

RUN DATE: June 2, 2006

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 166 | 134 | 144 |
| 2 | 165 | 135 | 144 |
| 3 | 155 | 135 | 142 |
| 4 | 160 | 132 | 143 |
| 5 | 156 | 128 | 140 |
| 6 | 150 | 131 | 138 |
| 7 | 157 | 128 | 140 |
| 8 | 154 | 126 | 134 |
| 9 | 144 | 124 | 134 |
| 10 | 144 | 125 | 134 |
| 11 | 157 | 127 | 137 |
| 12 | 151 | 128 | 139 |
| 13 | 158 | 122 | 135 |
| 14 | 139 | 118 | 130 |
| 15 | 145 | 122 | 131 |
| 16 | 151 | 119 | 132 |
| 17 | 147 | 116 | 132 |
| 18 | 162 | 115 | 131 |
| 19 | 136 | 117 | 126 |
| 20 | 142 | 114 | 122 |
| 21 | 143 | 114 | 125 |
| 22 | 137 | 118 | 125 |
| 23 | 151 | 115 | 126 |
| 24 | 145 | 119 | 128 |
| 25 | 149 | 119 | 131 |
| 26 | 154 | 122 | 135 |
| 27 | 150 | 124 | 133 |
| 28 | 146 | 123 | 132 |
| 29 | 151 | 124 | 134 |
| 30 | 157 | 126 | 138 |
| 31 | 169 | 127 | 146 |

Comments:

0 reading indicates that the station was out of service.