

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

VICTORIA CANAL ON THE MIDDLE RIVER

SEPTEMBER 2012

WATER QUALITY REPORT

RUN DATE: November 15, 2012

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|------------|-------------|------------|-------------|
| 1 | 288 | 281 | 284 |
| 2 | 289 | 282 | 286 |
| 3 | 305 | 284 | 288 |
| 4 | 297 | 289 | 291 |
| 5 | 301 | 293 | 297 |
| 6 | 307 | 297 | 303 |
| 7 | 312 | 301 | 305 |
| 8 | 322 | 303 | 310 |
| 9 | 325 | 306 | 313 |
| 10 | 328 | 310 | 315 |
| 11 | 326 | 313 | 318 |
| 12 | 341 | 319 | 325 |
| 13 | 351 | 329 | 333 |
| 14 | 356 | 338 | 343 |
| 15 | 367 | 348 | 353 |
| 16 | 370 | 356 | 364 |
| 17 | 387 | 366 | 376 |
| 18 | 396 | 378 | 387 |
| 19 | 401 | 386 | 394 |
| 20 | 416 | 399 | 404 |
| 21 | 416 | 405 | 408 |
| 22 | 418 | 407 | 411 |
| 23 | 421 | 413 | 417 |
| 24 | 425 | 417 | 419 |
| 25 | 427 | 418 | 420 |
| 26 | 424 | 414 | 418 |
| 27 | 419 | 411 | 415 |
| 28 | 421 | 407 | 412 |
| 29 | 419 | 402 | 409 |
| 30 | 414 | 402 | 407 |

Comments:

0 reading indicates that the station was out of service.