

UNITED STATES DEPARTMENT OF THE INTERIOR
U.S. BUREAU OF RECLAMATION-CENTRAL VALLEY PROJECT-CALIFORNIA

VICTORIA CANAL ON THE MIDDLE RIVER

SEPTEMBER 2019

WATER QUALITY REPORT

RUN DATE: October 8, 2019

ELECTRICAL CONDUCTIVITY, UMHOS

| DAY | HIGH | LOW | MEAN |
|-----|------|-----|------|
| 1 | 198 | 181 | 185 |
| 2 | 192 | 184 | 187 |
| 3 | 216 | 187 | 194 |
| 4 | 212 | 194 | 199 |
| 5 | 203 | 192 | 199 |
| 6 | 200 | 192 | 197 |
| 7 | 195 | 187 | 191 |
| 8 | 188 | 181 | 185 |
| 9 | 189 | 175 | 181 |
| 10 | 183 | 175 | 179 |
| 11 | 190 | 176 | 180 |
| 12 | 192 | 177 | 182 |
| 13 | 208 | 180 | 187 |
| 14 | 206 | 187 | 197 |
| 15 | 205 | 194 | 200 |
| 16 | 204 | 189 | 194 |
| 17 | 208 | 187 | 195 |
| 18 | 205 | 187 | 192 |
| 19 | 200 | 189 | 193 |
| 20 | 216 | 196 | 204 |
| 21 | 223 | 206 | 214 |
| 22 | 227 | 202 | 218 |
| 23 | 221 | 208 | 215 |
| 24 | 214 | 199 | 206 |
| 25 | 217 | 202 | 206 |
| 26 | 215 | 192 | 198 |
| 27 | 206 | 189 | 196 |
| 28 | 201 | 187 | 191 |
| 29 | 194 | 185 | 188 |
| 30 | 204 | 174 | 188 |

Comments:

0 reading indicates that the station was out of service.