



Pumping Plant with completed service yard, January 28



California Aqueduct turnout, January 28



Completed Intertie Site (facing north), January 28



West side of Pumping Plant, January 30



**At top - February 3rd divers work on canal lining replacement
At bottom - February 27th, finished canal lining**



Inside north 108" pipeline looking west toward 60" slide gate



Point-to-Point wiring checkout occurred through February



69 kV breaker test; required prior to energizing