



**Pumping Plant after a June Rain Event**



**Contractor Checking Torque of Nuts on 60" Flange Upstream of Energy Dissipator**



**Blind Flange attached on downstream end of Energy Dissipator**



**Installing pile for shoring at California Aqueduct Cofferdam**



**Removing 4" concrete liner at California Aqueduct**



**Excavated footprint of Turnout Structure at California Aqueduct**



**Checking Rebar of Concrete Encasement of 72" Steel Manifold**



**Pumping Plant as of Mid June 2011**



**Installing Bolts on 108" Steel Manifolds**



**Pumping Plant by End of June 2011**