

**Trinity River Channel Rehabilitation Site:
Deep Gulch (River Mile 82.4–82.9) and Sheridan Creek (River Mile 81.6–82.4)**

Environmental Assessment/Initial Study
DOI-BLM-CA-N060-2017-014-EA and TR-EA0117
State Clearinghouse #2008032110

Acronyms and Abbreviations.....iv

Chapter 1. Introduction and Background	1-1
1.1 Location of Rehabilitation Sites.....	1-1
1.2 Trinity River Restoration Program Background.....	1-3
1.3 Purpose and Need/Project Objectives	1-4
1.4 Purpose of This Document.....	1-5
1.5 Other Regulatory Requirements	1-7
1.6 Scoping and Public Involvement	1-8
Chapter 2. Description of Alternatives	2-1
2.1 Proposed Action.....	2-1
2.1.1 Activity A (Recontouring and Vegetation Removal)	2-1
2.1.2 Activities B, C, and D (Construction of Inundated Surfaces).....	2-2
2.1.3 Activities E and F (Side Channels)	2-2
2.1.4 Activity G (Alcoves).....	2-2
2.1.5 Activity H (Grade Control Removal)	2-3
2.1.6 Activity I (Sediment Management, Coarse and Fine).....	2-3
2.1.7 Activity J (Placement of Excavated Materials).....	2-3
2.1.8 Activity K (Staging/Contractor Use Areas)	2-3
2.1.9 Activities L and M (Roads, Existing and New)	2-4
2.1.10 Activity N (Temporary Channel Crossings)	2-4
2.1.11 Activity O (Revegetation).....	2-5
2.1.12 Detailed Master EIR Activities Described to Provide Additional Clarity Beyond That in Table 2-1	2-5
2.1.13 Design Considerations	2-7
2.1.14 Rehabilitation Activities	2-8
2.1.15 Revegetation Activities.....	2-26
2.1.16 Access and Other Associated Activities	2-28
2.1.17 Construction Methods and Schedule	2-32
2.1.18 Environmental Commitments	2-33
2.1.19 No Action Alternative.....	2-45
2.2 Alternatives Considered but Eliminated from Further Evaluation	2-45
Chapter 3. Affected Environment and Environmental Consequences	3-1
3.1 Introduction to the Analysis.....	3-1
3.2 Land Use	3-3
3.2.1 Affected Environment.....	3-3
3.2.2 Environmental Consequences	3-4
3.3 Recreation and Wild and Scenic Rivers.....	3-5
3.3.1 Affected Environment.....	3-5
3.3.2 Environmental Consequences	3-6
3.4 Visual Resources/Aesthetics.....	3-7
3.4.1 Affected Environment.....	3-7

3.4.2	Environmental Consequences	3-9
3.5	Cultural Resources	3-10
3.5.1	Affected Environment	3-11
3.5.2	Environmental Consequences	3-12
3.6	Transportation and Circulation.....	3-13
3.6.1	Affected Environment	3-13
3.6.2	Environmental Consequences	3-14
3.7	Air Quality.....	3-15
3.7.1	Affected Environment	3-15
3.7.2	Environmental Consequences	3-16
3.8	Noise.....	3-18
3.8.1	Affected Environment	3-18
3.8.2	Environmental Consequences	3-18
3.9	Geomorphology and Soils	3-20
3.9.1	Affected Environment	3-20
3.9.2	Environmental Consequences	3-22
3.10	Hydrology and Flooding	3-23
3.10.1	Affected Environment	3-23
3.10.2	Environmental Consequences	3-24
3.11	Water Quality	3-26
3.11.1	Affected Environment	3-26
3.11.2	Environmental Consequences	3-29
3.12	Fishery Resources.....	3-30
3.12.1	Affected Environment	3-31
3.12.2	Environmental Consequences	3-33
3.13	Vegetation, Wildlife, and Wetlands	3-36
3.13.1	Affected Environment	3-36
3.13.2	Environmental Consequences	3-39
3.14	CEQA Significance	3-50
Chapter 4.	Cumulative Impacts and Other CEQA and NEPA Considerations.....	4-1
4.1	Cumulative Impacts.....	4-1
4.1.1	Methodology and Analysis.....	4-1
4.2	Irreversible and Irretrievable Commitments of Resources.....	4-4
4.3	Relationship between Local Short-Term Uses of the Environment and the Maintenance and Enhancement of Long-Term Productivity	4-5
4.4	Growth-Inducing Impacts.....	4-5
4.5	Environmental Commitments and CEQA Mitigation Measures.....	4-6
4.6	Significant Impacts under CEQA	4-6
4.7	Connected Actions	4-6
Chapter 5.	List of Preparers.....	5-1
Chapter 6.	References	6-1

Tables

Table 2-1.	Overview of Activity Areas at Deep Gulch and Sheridan Creek Rehabilitation Sites	2-11
Table 2-2.	Material Types	2-14
Table 2-3.	Processed Material by Size Class	2-14
Table 2-4.	Woody Material Used for Rehabilitation Activities	2-15
Table 2-5.	Environmental Commitments	2-34
Table 3-1.	Summary of Resource Topics Considered or Eliminated from Further Consideration in This EA/IS.....	3-2
Table 3-2.	Existing Condition WUA for Fry and Presmolt Habitat – Deep Gulch and Sheridan Creek Sites.....	3-32
Table 3-3.	Proposed Action WUA for Fry and Presmolt Habitat – Deep Gulch and Sheridan Creek Sites.....	3-35
Table 3-4.	Increase in WUA Habitat Under the Proposed Action– Deep Gulch and Sheridan Creek Sites.....	3-35
Table 3-5.	Wildlife Habitats in the Project Area.....	3-37
Table 3-6.	Summary of Waters of the U.S. Within the Project Area.....	3-38
Table 3-7.	Summary of Resource Topics Considered in This EA/IS	3-50
Table 4-1.	Summary of Cumulative Impacts Considering Past, Present and Reasonably Foreseeable Actions in the Trinity River Basin.....	4-3

Figures

Figure 1-1.	Location of Rehabilitation Sites	1-2
Figure 2-1.	Deep Gulch and Sheridan Creek Sensitive Areas.....	2-9
Figure 2-2.	Proposed Rehabilitation Activities	2-29
Figure 3-1a.	Impacts on Waters of the United States.....	3-41
Figure 3-1b.	Impacts on Waters of the United States.....	3-43
Figure 3-2a.	Impacts on Riparian Habitat	3-45
Figure 3-2b.	Impacts on Riparian Habitat	3-47

Appendices

(Note: All appendices are provided on a CD at the back of this report.)

Appendix A1	Environmental Screening Checklist
Appendix A2	Environmental Checklist Form
Appendix B	Comments and Responses to Comments on the Draft EA/IS
Appendix C	Aquatic Conservation Strategy Consistency Evaluation
Appendix D	Mitigation Monitoring and Reporting Program and Project Design Features
Appendix E	Compliance with Standards and Guidelines for Survey and Manage Species
Appendix F	Wild and Scenic River, Section 7 Analysis and Determination