# RECLAMATION

Managing Water in the West

# Proposed Experiment in Evaluating Filter Material and Water Chemistry for Potential of Promoting Bacterial Growth Resulting in Clogged Drains

Research and Development Office Science and Technology Program Final Report ST-2015-7101-1



Audrey Rager MERL-2015-106



U.S. Department of the Interior Bureau of Reclamation Research and Development Office

# **Mission Statements**

The U.S. Department of the Interior protects America's natural resources and heritage, honors our cultures and tribal communities, and supplies the energy to power our future.

The mission of the Bureau of Reclamation is to manage, develop, and protect water and related resources in an environmentally and economically sound manner in the interest of the American public.

					OMB No. 0704-0188
T1. REPORT DATI	E Dec. 2015	2. REPORT TYPE	Research	T3.	DATES COVERED
	ent in Evaluating Fi		ater Chemistry for Po		<b>CONTRACT NUMBER</b> R0680A1-RY1541IR201517101
of Promoting Bacte	rial Growth Resulti	ng in Clogged Drair	ns	5b.	GRANT NUMBER
					PROGRAM ELEMENT NUMBER 1541 (S&T)
6. AUTHOR(S)				5d.	PROJECT NUMBER
Audrey Rager, 3	303-445-2377, araç	ger@usbr.gov			7101
				5e.	TASK NUMBER
					WORK UNIT NUMBER 86-68530
7. PERFORMING		` '	` '	8. F	PERFORMING ORGANIZATION
Audrey Rager, U.S. Bureau of Reclamation, Denver, CO					PORT NUMBER MERL-2015-107
		• •	ND ADDRESS(ES)	10.	SPONSOR/MONITOR'S
Research and D				RONYM(S)	
•	nt of the Interior, Bu Denver CO 80225	reau of Reclamation	n,	R& Off	D: Research and Development
1 O Box 23007,	Deliver CO 00223	-0001		_	R/USBR: Bureau of Reclamation
					I: Department of the Interior
					SPONSOR/MONITOR'S REPORT JMBER(S)
				ST-	2015-7101-1
12. DISTRIBUTION Final report car			's website: https://v	www.usbr.go	v/research/
13. SUPPLEMENT	ARY NOTES				
14. ABSTRACT (M					
was outlined to test how	various filter materials ch and Development of	and water chemistry con	nditions result in bacteria	growth. The expe	acterial growth in toe drains. An experiment erimental methods were outlined and oposal was not funded. This report is a
15. SUBJECT TER Embankment dams		ns, clogged drains			
16. SECURITY CL			17. LIMITATION	18. NUMBER	R 19a. NAME OF RESPONSIBLE
			OF ABSTRACT	OF PAGES	PERSON
a. REPORT	b. ABSTRACT U	<b>c. THIS PAGE</b> U	U		19b. TELEPHONE NUMBER 303-445-2125
		L	1	l	

REPORT DOCUMENTATION PAGE

S Standard Form 298 (Rev. 8/98) P Prescribed by ANSI Std. 239-18

Form Approved

## PEER REVIEW DOCUMENTATION

### **Project and Document Information**

Project Name Evaluating Filter Material and Water	Chemistry for Potential for Promoting					
Bacterial Growth Resulting in Clogged Drains	WOID <u>Z7101</u>					
Document Proposed Experiment for Evaluating F	ilter Material and Water Chemistry for					
Potential for Promoting Bacterial Growth Resulting in Clogged Drains						
Document Author(s) Audrey Rager	Document date <u>12/30/2015</u>					
Peer Reviewer <u>Denise Hosler</u>						

### **Review Certification**

**Peer Reviewer:** I have reviewed the assigned items/sections(s) noted for the above document and believe them to be in accordance with the project requirements, standards of the profession, and Reclamation policy.

Reviewer Mais M. Hoslu Date reviewed 12/29/2015

# **EXECUTIVE SUMMARY**

The goal of this S&T project was to develop recommendations for future studies into the conditions that promote bacterial growth in toe drains. An experiment was outlined to test how various filter materials and water chemistry conditions result in bacteria growth. The experimental methods were outlined and submitted to the Research and Development office for funding during FY2016 (Project ID: 3125). The research proposal was not funded. This report is a summary of that proposal and experiment.

#### **Research Question**

Bacterial grown in the drainage systems of embankment dams can clog drains resulting in costly repairs. What conditions promote this bacterial growth in drainage systems of embankment dams and how can we modify our evaluation of filter material to reduce the chance of bacterial growth and promote infrastructure reliability?

#### Mission Responsibility

Because there is no standard for evaluating gravel and sand for use as filter material, the current policy is to follow ASTM C295 (Standard Guide for Petrographic Examination of Aggregates for Concrete). There are special concerns for filter materials; therefore, C295 may be inadequate for this purpose. During 2013, several samples from clogged dam drains were submitted to the MERL Petrography Lab to determine the cause of the clogging. In most cases, the problem turned out to be sludge and mineral precipitates from iron and sulfur bacteria which thrive under certain conditions.

# **Research Strategy**

The proposed experiment involves building ten toe drain models and testing five types of filter material. These proposed materials include quartz sand, sand samples used in two embankment dams with a history of drain clogging from bacterial growth (Los Banos and Mt. Elbert/Twin Lakes), and two sand sources proposed for use in the Lake Isabella dam. Each sand sample with be autoclaved before being placed in two toe drain models, one control and one treatment. Each of the five control toe drains will include tap water, while a sample of bacteria-bearing water from an acid-mine drainage in Idaho Springs will be introduced to the five treatment models. Bacterial growth will be monitored for six months to one

year. Results will be documented with photos, graphs, and tables and a final report.

In addition to the proposed experiment, a literature review should be conducted to determine levels of iron sulfide and other iron- and sulfurbearing minerals that would induce bacterial growth and set a standard for acceptable levels of these minerals, as well as the water chemistry necessary for their growth. The ultimate goal would be to incorporate these results into a new standard for the petrographic evaluation of gravel and sand for use as filter material.

#### **Need and Benefit**

In the past several years, many samples from clogged dam drains were submitted to the MERL Petrography Lab to determine the cause of the clogging. In most cases, the problem turned out to be sludge and mineral precipitates from iron and sulfur bacteria which thrive under certain conditions. There is currently no ASTM standard for the petrographic evaluation of sand as filter material in embankment dams. The proposed experiment was designed to determine what types of rocks and minerals promote the growth of bacteria that clog drains.