

LIST OF FIGURES

- Figure 1 Location map displaying San Acacia reach location and weather station locations.
- Figure 2 Faulted surface (fault #1 is upstream of fault #4) along the Rio Grande, San Acacia Reach.
- Figure 3 Average Monthly Discharges – USGS Rio Grande gage at the San Acacia Floodway
- Figure 4 Average Monthly Suspended Sediment – USGS Rio Grande gage at the San Acacia Floodway.
- Figure 5 Cumulative Snowfall Records in Southern Colorado.
- Figure 6 Yearly Total Precipitation at Socorro, NM and Bernardo, NM.
- Figure 7 Annual discharge given in year discharge and cumulative – USGS Rio Grande gage at San Acacia, NM.
- Figure 8 Annual sediment load given in year discharge and cumulative – USGS Rio Grande gage at San Acacia, NM.
- Figure 9 Cumulative suspended sediment and discharge – USGS Rio Grande gages at San Acacia, NM and San Marcial, NM.
- Figure 10 Historic Well Logs in the San Acacia Reach.
- Figure 11a Sub-Reach location map showing Sub-reaches 1, 2 and the northern portion of sub-reach 3, Rio Grande – San Acacia Reach.
- Figure 11b Sub-Reach location map showing the southern portion of sub-reach 3 and sub-reach 4, Rio Grande – San Acacia Reach.
- Figure 12 Terraced surfaces along the Rio Grande – San Acacia Reach.
- Figure 13 Stratigraphic columns of two terraces along the Rio Grande - San Acacia Reach.
- Figure 14 Flood frequency curve, Rio Grande – San Acacia Reach.
- Figure 15a Historic trends in channel location, Rio Grande – San Acacia Reach: 1918, 1935, 1949 channel locations.
- Figure 15b Historic trends in channel location, Rio Grande – San Acacia Reach: 1918, 1962, 1972 channel locations.
- Figure 15c Historic trends in channel location, Rio Grande – San Acacia Reach: 1918, 1985, 1992 and 2002 channel locations.
- Figure 16 Historic trends in channel Sinuosity, Rio Grande – San Acacia Reach.
- Figure 17 Historic channel width, Rio Grande – San Acacia Reach.
- Figure 18 Channel widths and overbanking since 1962, Rio Grande – San Acacia reach.
- Figure 19 Bed Material Measurements at the USGS Rio Grande gage, San Acacia.
- Figure 20 Monthly variability in grain sizes at the USGS Rio Grande gage, San Acacia.
- Figure 21 Particle size distribution of gravel layer, Rio Grande – San Acacia Reach.
- Figure 22 Estimated sand load results from the modified Einstein procedure, Rio Grande gage at San Acacia.
- Figure 23 Sediment Transport Zone Locations, Rio Grande – San Acacia Reach

- Figure 24 USGS Rio Grande gage (at San Acacia) discharge data for a wet year (1994) and the corresponding sediment discharge.
- Figure 25 USGS Rio Grande gage (at San Acacia) discharge data for a dry year (1996) and the corresponding sediment discharge.
- Figure 26 USGS Rio Grande gage (at San Acacia) discharge data for a 5-year period (1990-1995) and the corresponding sediment discharge.
- Figure 27 Future elevation conditions of Sub-Reach 4, Rio Grande – San Acacia Reach.
- Figure 28 Three USBR river maintenance priority sites with levee erosion concerns, plus one site of estimated future levee erosion (the downstream most highlighted section), Rio Grande; San Acacia Reach.